Print View (https://www.tdlr.texas.gov/TABS/Search/Print/TABS2025024267)



# Texas Department of Licensing and Regulation Architectural Barriers Project Details Page

Registration Date: 7/24/2025

Project #: TABS2025024267

https://www.tdlr.texas.gov/TABS/Projects/TABS2025024267 (https://www.tdlr.texas.gov/TABS/Projects/TABS2025024267)

# **PROJECT**

## **Project Name:**

Haverstock Hills Apartments (WEST)

## **Project Number:**

TABS2025024267

## **Facility Name:**

Haverstock Hills

#### **Location Address:**

5619 Aldine Bender

Houston, TX 77032

# **Location County:**

Harris

### Start Date:

12/1/2025

#### **Completion Date:**

5/1/2026

#### **Estimated Cost:**

\$100,000

## Type of Work:

Renovation/Alteration

#### Type of Funds:

This project involves public funds, public land, or is a Federally funded roadway project.

## Scope of Work:

The scope of the renovations will include interior renovations and replacing components that are in disrepair. The property will also be brought up to applicable accessibility standards.

## **Square Footage:**

6,541 ft <sup>2</sup>

## Are the private funds provided by the tenant?

No

## **Current Status:**

Project Registered

	1 A				
PERSC	N	FIL	IING	FOI	≺IVI

**Contact Name:** 

Theresa Bartlett

#### RAS

**RAS Name:** 

HOLLY, RESPONDEK

RAS #:

39

**RAS Address:** 

110 S MECHANIC ST #1413

EL CAMPO, TX 77437

**RAS Phone:** 

(979) 257-8432

#### **OWNER**

Owner Name:

**Brendan Tarang** 

**Owner Address:** 

1700 N Broadway Suite 810

Denver, Colorado 80290

**Owner Phone:** 

(303) 596-5944

**Contact Name:** 

Brendan Tarang

# **TENANT**

Not Assigned

#### DESIGN FIRM

Not Assigned

Registered accessibility specialists (RAS) set and collect the fees for their services. Contact the RAS directly if you have questions about their performing plan review or inspection services.

In accordance with 16 TEX. ADMIN. CODE §68.52, the owner of a building or facility must obtain an inspection from a RAS no later than the first anniversary of the completion of construction. A request for inspection must be made by submitting a written request for inspection to the RAS no later than 30 calendar days after the completion of construction.

Print View (https://www.tdlr.texas.gov/TABS/Search/Print/TABS2025024267)

Privacy and Security Policy Compact with Texans Texas Homeland Security (https://www.tdlr.texas.gov/disclaimer.htm/https://www.tdlr.texas.gov/compact.htm) (http://governor.state.tx.us/homeland)

Accessibility Report Suspected Fraud, Waste, or Texas Transparency

(https://www.tdlr.texas.gov/disclaimer.htm**#laose**ss) (http://www.texastransparency.org/)

Open Records Policy (https://www.tdlr.texas.gov/disclaimer.htm###rassdy/eterans Portal

(https://www.tdlr.texas.gov/disclaimer.htm###xatslightfofffbtjisy//www.texas.gov) (https://veterans.portal.texas.gov/)

Link Policy Statewide Search Contact TDLR

(https://www.tdlr.texas.gov/disclaimer.htm///www.tsl.texas.gov/trail/index.html)(https://www.tdlr.texas.gov/contact.ht

8/6/25, 4:33 AM Project Details



# Texas Department of Licensing and Regulation Architectural Barriers Project Details Page

Project #: TABS2025024266 Registration Date: 7/24/2025

https://www.tdlr.texas.gov/TABS/Projects/TABS2025024266

#### **PROJECT**

Project Name: Haverstock Hills Apartments (EAST)

Project Number: TABS2025024266
Facility Name: Haverstock Hills
Location Address: 5619 Aldine Bender

Houston, TX 77032

 Location County:
 Harris

 Start Date:
 12/1/2025

 Completion Date:
 5/1/2026

 Estimated Cost:
 \$100,000

Type of Work: Renovation/Alteration

Type of Funds: This project involves public funds, public land, or is a Federally funded roadway project.

Scope of Work: The scope of the renovations will include interior renovations and replacing components that are in disrepair. The

property will also be brought up to applicable accessibility standards.

Square Footage: 6,541 ft <sup>2</sup>

Are the private funds No

provided by the tenant?

Current Status: Project Registered

PERSON FILING FORM

Contact Name: Theresa Bartlett

**RAS** 

RAS Name: HOLLY, RESPONDEK

**RAS** #: 39

RAS Address: 110 S MECHANIC ST #1413

EL CAMPO, TX 77437

**RAS Phone:** (979) 257-8432

OWNER

Owner Name: Haverston Hills Preservation East, LLC

Owner Address: 1700 N Broadway Suite 810

Denver, Colorado 80290

Owner Phone: (303) 596-5944
Contact Name: Brendan Tarang

**TENANT** 

Not Assigned

#### **DESIGN FIRM**

Not Assigned

Registered accessibility specialists (RAS) set and collect the fees for their services. Contact the RAS directly if you have questions about their performing plan review or inspection services.

In accordance with 16 TEX. ADMIN. CODE §68.52, the owner of a building or facility must obtain an inspection from a RAS no later than the first anniversary of the completion of construction. A request for inspection must be made by submitting a written request for inspection to the RAS no later than 30 calendar days after the completion of construction.